

## Waste Site Reclassification Form

<b>Date Submitted:</b> 6/2/2004	<b>Operable Unit(s):</b> 200-UR-1	<b>Control Number:</b> 2004-067
<b>Originator:</b> C. R. Webb	<b>Waste Site ID:</b> 200-E-54	
<b>Phone:</b> 373-5574	<b>Type of Reclassification Action:</b> Rejected: <input checked="" type="radio"/> No Action: <input type="radio"/> Interim Closed Out: <input type="radio"/> Closed Out: <input type="radio"/>	

This form documents agreement among the parties listed below authorizing classification of the subject unit as rejected, closed-out, or no action and authorizing backfill of the site, if appropriate. Final removal from the NPL of no action or closed-out sites will occur at a future date.

**Description of current waste site condition:**



The site is an unplanned release to the environment that occurred in January 1991, as a result of a raw water line rupture in the basement of the 293-A Building, south of the 202 A Building. The water backed up into the PUREX Canyon exhaust ventilation ductwork, including the #1 deep bed fiberglass filter, until approval to transfer the liquid to the tank farms was given in September 1992.

**RECEIVED**  
FEB 8 2005

**EDMC**

**Basis for reclassification:**

This site is recommended for Reject (consolidated) status with 200-E-103, Contamination Areas - South Side of PUREX. Site 200-E-103 is an area where a number of releases occurred. Based on the original release estimate of 380,000 liters (100,000 gallons), it is believed that 201,400 liters (53,000 gallons) leaked to the soil over the 21 months from the release date to the date the liquid was transferred. Any residual radioactive material that may be remaining will be decontaminated with 200-E-103.

<b>STEVE BOETTNER</b> DOE Project Manager	 Signature	6/30/04 Date
<b>John B. Price</b> Ecology Project Manager	 Signature	6/30/04 Date
<b>N/A</b> EPA Project Manager	 Signature	 Date